

Server Name : AWS New Prod AWSPPRDDG Claims loaded through 02-MAR-2012

**ANALYTICAL WARRANTY SYSTEM**[Home](#) | [Overview](#) | [Statistics](#) | [Documentation](#) | [Download](#) | [Online Reports](#) | [Utilities](#) | [Contact Us](#)**Standard Claims List For Model Year 2002**

Note: All Costs are in US Dollars

VIN	VEH LINE	MKT DERIV	BODY CAB	VER SERIES	PLT TYPE	TRS CD	ENG CD	PROD DATE	WARR DATE	SELLING DEALER	SELL CNT	TIS	WCC	CPSC_6	PREF	BASE	SUFF	VRT NA	VRT ROW	VFG	CCC	CD	DIST(Miles)
IFTNW20F72EA52347	T/F7	F	T/BC	T/BD	T/B	A1	T/D8	T/DS 30-AUG-2001	02-JUN-2002	152032	USA	35	2H01	030008	*	6K682	*	F04	S11	V44	L65	D8	99890
AWS Claim Key:	13193766	Trx Code:	E72	Labor Hrs:	1.5	Labor Cost:	127.05	Material Cost:	6.15	Total Cost:	133.2												
Dlr Cd-Sub Cd:	05508-*	Name:	THEODORE ROBINS, INC.			Ph:	949-6420010		St:	CA	Ctry Cd:	USA	Reg Cd:	NA	Repr Date:	30-MAR-2005	Doc #:	07813151					
Cust Comments:	CUSTOMER STATES OIL LEAKING FROM FRONT TOP REAR OF ENGINE, CK AND ADVISE																						
Tech Comments:	DIAGNOSE OIL LEAK TOP OF ENGINE INSTALL OIL DYE AND ROAD TEST INSPECT FOR OIL LEAKING TOP OF ENGINE NO DYE PRESENT AFTER CONVERSATION WITH CUSTOMER CAC TUBE SEALS LOOSE AND SOURCE OF OIL AT TOP OF ENGINE NORMALCONDITION UNDER HEAVY LOAD CONDITION REMOVE CAC TUBE SEALS AND CLEAN TUBES REINSTALL SEALS RETORQUE CLAMPS CLEAN ENGINE OF OIL AND RETEST FOUND NO OTHER OIL LEAKS PRESENT																						
IFTNW20F72EA52347	T/F7	F	T/BC	T/BD	T/B	A1	T/D8	T/DS 30-AUG-2001	02-JUN-2002	152032	USA	78	*	*	*	*	*	F09	SXX	V00	*	*	177052
AWS Claim Key:	17066671	Trx Code:	07S57	Labor Hrs:	3	Labor Cost:	29.53	Material Cost:	17.4	Total Cost:	46.93												
Dlr Cd-Sub Cd:	05508-*	Name:	THEODORE ROBINS, INC.			Ph:	949-6420010		St:	CA	Ctry Cd:	USA	Reg Cd:	NA	Repr Date:	13-OCT-2008	Doc #:	05072940					
Cust Comments:	07S57 CAMSHAFT POSITION (CMP) SENSOR INSPECTION REPLACEMENT																						
Tech Comments:	RECALL 07S57B REPLACE CMMP SENSOR																						
IFTNW20F72EA52347	T/F7	F	T/BC	T/BD	T/B	A1	T/D8	T/DS 30-AUG-2001	02-JUN-2002	152032	USA	101	*	*	*	*	*	F09	SXX	V00	*	*	188358
AWS Claim Key:	17911162	Trx Code:	09S09	Labor Hrs:	2	Labor Cost:	20.34	Material Cost:	10.42	Total Cost:	30.76												
Dlr Cd-Sub Cd:	05508-*	Name:	THEODORE ROBINS, INC.			Ph:	949-6420010		St:	CA	Ctry Cd:	USA	Reg Cd:	NA	Repr Date:	16-SEP-2010	Doc #:	08161440					
Cust Comments:	09S09 SPEED CONTROL SYSTEM MODIFICATION																						
Tech Comments:	09S09 INSTALL WIRE																						

[Any comments?](#)